

Work Order ID 51471

September 03, 2009 2:54:41 PM



Page 1

Item ID: D3572-041

Accept



Setup Start



Revision ID: A

Stop



Item Name: Guide Assembly

Start Date: 08/25/09 Start Qty: 2.00



Cust Item ID:

Required Date: 08/31/09 Req'd Qty: 2.00



Customer:

Reference: Return 2009/RA109075/R09-075

Run Start



Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Stop



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	----------------	--------------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3572	Rev A

230 QC5- Inspect part completeness to step on W/O 0.00



QC

Quality Control

Memo

0.00

Original D3572-041 B40532. Parts are in good condition, and to return back to stock. Parts are Rev.C

2

09-05-03

240 Identify as per dwg & Stock Location: 260 0.00



Packaging

Packaging

Memo

0.00

Return to stock with the new batch #.

2

Pc 9/1/09

250 QC21- Final Inspection - Work Order Release 0.00



QC

Quality Control

Memo

0.00

09/09/08

BP 09-9-09

Picklist Print

Page 1

September 03, 2009 2:54:41 PM

Work Order ID: 51471



Parent Item: D3572-041RevA



Parent Item Name: Guide Assembly

Start Date: 08/25/09

Required Date: 08/31/09

Comments:

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3572-041RevA		Manufactured	No				Each	2.0000	2.0000 ✓			

Guide Assembly

Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

Return 2009

40532

2

2 ✓

PC9/2/4